Flock Audio PATCH APP DX 1.1.2



Flock Audio announces PATCH APP DX 1.1.2 – the latest version of Flock's control app for its series of best-in-class all-analog, digitally controlled patchbays. PATCH APP DX 1.1.2 adds several long-requested features that further streamline its functionality in terms of signal flow, multi-unit operation, gain control, and recall.

"With every update we've continued to streamline the experience of PATCH APP DX and make it faster and easier to use than ever before – whether you are using a single unit in a small project studio or multiple PATCH XTs in a studio complex," said Flock Audio Founder and CEO Darren Nakonechny. "This latest version of PATCH APP DX adds some long-awaited convenience features that were directly sourced from the feedback of our user community,."

PATCH APP DX Improvements (v1.1.2):

- New Feature: Grouping – Ability to Setup Groups So iOS Devices can Control only specific PATCH Series Hardware
- New Feature: CX - Adjust CX Gain Levels right from the active routing grid by "Right Clicking" on a CX Connected Device.
- New Feature: CX – Various Gains for the same Microphone or Instrument can now be saved on a per routing file basis, instead of just fixed to 1 specific Mic or Instrument.
- New Feature: CX (User Preferences) - Option for Vertical or Radial Adjustments

Phoca PDF

- Improvement: Hardware Setup Locks/Unlocks - Improved Visual Contrast
- New Feature: Bump – Place Selections in the Active Routing Grid by Dragging & Dropping These Selections from your Hardware Index over the Green Active Icon and it will bump the other Selections down in the Signal Path.
- New Feature: Multi-Unit Setup – Optional Toggle to Turn off the need to Drag + Drop “Sends & Returns” in the Active Routing Grid when using Multi-Unit Setups. Note this must be activated in the User Preference Section.
- Key Command – Press Escape Key to clear any search fields
- Key Command – OSX (Cmd + F) or Windows (Crtl + F) will Select Any Window or Menu’s Search Field

Bug Fixes

- Fixed: Folder graphics fix on reopening window
- Fixed: Remove save button from cx window when no cx present
- Fixed: Multi Unit device connection re-ordering issue
- Fixed: allow for special characters like “ / “ in file names to work correctly
- Fixed: Empty Routing Names will not be Hidden when selecting “Display Unassigned in Hardware Index”
- Fixed: Multiple DX Host Conflict Resolution
- Fixed: Multiple PATCH XT’s Load time on PATCH APP DX Corrected

www.flockaudio.com

Phoca PDF